



Factory Inspection Certificate

Certificate no.: **MIEB_78642-001-00** Valid from: **2025-09-11**
until: **2026-12-31**

Manufacturer/Applicant: **DAS Energy Ltd. Niederlassung Österreich**
Ferdinand Graf von Zeppelin Strasse 18
2700 Wiener Neustadt
Austria

Product: **PV Module**

Trademark: **DAS Energy**

Model(s) ⁽¹⁾: **...M102 HYB (for detailed information see pages 1 and 2 of Annex to Certificate)**
...M102 GFK (for detailed information see pages 3 and 4 of Annex to Certificate)
...M3 GFK (for detailed information see pages 5 and 6 of Annex to Certificate)

It is confirmed that the following main production steps are taking place in the European manufacturing plant(s) as listed in the annex to this certificate ⁽²⁾:

- Incoming inspection
- Adding of foil or glass
- String process (soldering)
- Lamination process
- Wiring process
- Testing of the modules

This certificate has been issued based on the results of on-site inspections and/or documented evidence provided by the manufacturer in accordance with the information specified in the annex. It does not authorize to use any mark of conformity on any of the products. It may be used to apply for the listing of products for the Austrian Made in Europe Bonus in accordance with ordinance BGBl. II Nr. 76/2025.

This certificate is only valid if the relevant production facilities remain unchanged. Any changes must be reported and may result in a reassessment.

Österreichischer Verband für Elektrotechnik
Head of OVE Certification

T. Neumayer

Digitally signed by T. Neumayer
Email=t.neumayer@ove.at

Dipl.-Ing. T. Neumayer



Wien, 2025-09-11

OVE Certification



Annex to Certificate No. MIEB_78642-001-00
 Date: 2025-09-11

Annex Page 1 of 6

Product: **PV Module**

Trademark: **DAS Energy**

Model(s): **6x1M102 HYB, 6x2M102 HYB, 6x3M102 HYB, 6x4M102 HYB, 6x5M102 HYB, 7x1M102 HYB, 7x2M102 HYB, 7x3M102 HYB, 7x4M102 HYB, 7x5M102 HYB, 8x1M102 HYB, 8x2M102 HYB, 8x3M102 HYB, 8x4M102 HYB, 8x5M102 HYB, 9x1M102 HYB, 9x2M102 HYB, 9x3M102 HYB, 9x4M102 HYB, 9x5M102 HYB, 10x1M102 HYB, 10x2M102 HYB, 10x3M102 HYB, 10x4M102 HYB, 10x5M102 HYB, 11x1M102 HYB, 11x2M102 HYB, 11x3M102 HYB, 11x4M102 HYB, 11x5M102 HYB, 12x1M102 HYB, 12x2M102 HYB, 12x3M102 HYB, 12x4M102 HYB, 12x5M102 HYB, 14x1M102 HYB, 14x2M102 HYB, 14x3M102 HYB, 14x4M102 HYB, 14x5M102 HYB, 16x1M102 HYB, 16x2M102 HYB, 16x3M102 HYB, 16x4M102 HYB, 16x5M102 HYB, 18x1M102 HYB, 18x2M102 HYB, 18x3M102 HYB, 18x4M102 HYB, 18x5M102 HYB, 20x1M102 HYB, 20x2M102 HYB, 20x3M102 HYB, 20x4M102 HYB, 20x5M102 HYB, 20x6M102 HYB, 22x1M102 HYB, 22x2M102 HYB, 22x3M102 HYB, 22x4M102 HYB, 22x5M102 HYB, 22x6M102 HYB**

Main production steps ⁽²⁾	Manufacturing plant / Supplier (Company name and address)	Objective evidence verified ⁽³⁾	Remarks
Incoming inspection	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed
Adding of foil or glass	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed
String process (soldering)	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed
Lamination process	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed

OVE Certification



Annex Page 2 of 6

Wiring process	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed
Testing of the modules	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed

(4)

OVE Certification



Annex Page 3 of 6

Product: **PV Module**

Trademark: **DAS Energy**

Model(s): **6x1M102 GFK, 6x2M102 GFK, 6x3M102 GFK, 6x4M102 GFK, 6x5M102 GFK, 7x1M102 GFK, 7x2M102 GFK, 7x3M102 GFK, 7x4M102 GFK, 7x5M102 GFK, 8x1M102 GFK, 8x2M102 GFK, 8x3M102 GFK, 8x4M102 GFK, 8x5M102 GFK, 9x1M102 GFK, 9x2M102 GFK, 9x3M102 GFK, 9x4M102 GFK, 9x5M102 GFK, 10x1M102 GFK, 10x2M102 GFK, 10x3M102 GFK, 10x4M102 GFK, 10x5M102 GFK, 11x1M102 GFK, 11x2M102 GFK, 11x3M102 GFK, 11x4M102 GFK, 11x5M102 GFK, 12x1M102 GFK, 12x2M102 GFK, 12x3M102 GFK, 12x4M102 GFK, 12x5M102 GFK, 14x1M102 GFK, 14x2M102 GFK, 14x3M102 GFK, 14x4M102 GFK, 14x5M102 GFK, 16x1M102 GFK, 16x2M102 GFK, 16x3M102 GFK, 16x4M102 GFK, 16x5M102 GFK, 18x1M102 GFK, 18x2M102 GFK, 18x3M102 GFK, 18x4M102 GFK, 18x5M102 GFK, 20x1M102 GFK, 20x2M102 GFK, 20x3M102 GFK, 20x4M102 GFK, 20x5M102 GFK, 20x6M102 GFK, 22x1M102 GFK, 22x2M102 GFK, 22x3M102 GFK, 22x4M102 GFK, 22x5M102 GFK, 22x6M102 GFK**

Main production steps ⁽²⁾	Manufacturing plant / Supplier (Company name and address)	Objective evidence verified ⁽³⁾	Remarks
Incoming inspection	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed
Adding of foil or glass	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed
String process (soldering)	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed
Lamination process	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed

OVE Certification



Annex Page 4 of 6

Wiring process	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed
Testing of the modules	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed

(4)

OVE Certification



Annex Page 5 of 6

Product: **PV Module**
 Trademark: **DAS Energy**
 Model(s): **10x2M3 GFK, 10x6M3 GFK,
 11x2M3 GFK, 11x3M3 GFK, 11x6M3 GFK
 12x2M3 GFK**

Main production steps ⁽²⁾	Manufacturing plant / Supplier (Company name and address)	Objective evidence verified ⁽³⁾	Remarks
Incoming inspection	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed
Adding of foil or glass	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed
String process (soldering)	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed
Lamination process	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed

OVE Certification



Annex Page 6 of 6

Wiring process	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed
Testing of the modules	DAS Energy Ltd. Niederlassung Österreich Ferdinand Graf von Zeppelin Strasse 18 2700 Wiener Neustadt Austria	On site inspection, 2025-07-18 OVE (MIEB_78642_20250718), Mr. Markus Obritzhauser	Production witnessed
	Lux Otimeyes Energy Pólo tecnológico de Lote 7860-076 Moura Portugal	Document audit during onsite inspection MIEB_78642_20250718 and follow up 2025-09-11	Processes witnessed

(4)

Further information ⁽⁵⁾:

Remarks:

- (1) Use additional page for further models (if necessary)
- (2) List the main production steps performed in a member state of the European Union or the European Economic Area or Switzerland
- (3) Examples for evidence: Production witnessed or records reviewed during Onsite inspections, Manufacturer's declaration from subsupplier (if acceptable) etc.
- (4) Use additional tables if necessary (for further products or production processes)
- (5) Optional, if necessary

OVE Certification